

LINDEMANN.

Update History

Update Release 2023 06 23

Streaming module update

Supported devices:

- Limetree BRIDGE I/II
- Limetree NETWORK I/II
- Musicbook SOURCE I/II
- Musicbook SOURCE Upgrade
- Musicbook COMBO

Revision: StreamSDK 2.16.0

Changes:

- FW optimized for new Lindemann App 2.0

Update Release 2023 01 17

Streaming module update

Supported devices:

- Limetree BRIDGE I/II
- Limetree NETWORK I/II
- Musicbook SOURCE I/II
- Musicbook SOURCE Upgrade
- Musicbook COMBO

Revision: StreamSDK 2.13.0/LIN_RB21_v22

Bugfix:

- Playback fails after random time

Update Release 2022 12 06

Streaming module update

Supported devices:

- Limetree BRIDGE I/II
- Limetree NETWORK I/II
- Musicbook SOURCE I/II
- Musicbook SOURCE Upgrade
- Musicbook COMBO

Revision: StreamSDK 2.11.0/LIN_RB21_v20

Changes:

- No audio on Multiroom slave for USB Audio-CD
- Update Spotify Connect Library

Device firmware update

Supported devices:

- Musicbook SOURCE I
- Musicbook SOURCE Upgrade

Revision: 2.08

Changes:

- No Tidal icon display when changing sources
 - Local sources are not switched correctly after start-up
-

Supported devices:

- Musicbook SOURCE II
- Musicbook COMBO

Revision: 2.08

Changes:

- Volume control range changed
- Sampler rate display for digital input has shown incorrect values
- Channel reversed Balance setting
- Local sources are not switched correctly after start-up